


Diagramas de Fase


CM3201-Ciencia de los Materiales I

Rodrigo Bahamondes S.


P1




P1




P1




P2-a




P2-a




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-b




P2-c




P3





P3b



P3c,d

